



SSM 52004 Various carlines - Cluster message Pre-Collision Assist is not available due to blocked sensor

If customer claims the above be informed that this can be caused by a temporary switch off the system to avoid misdetection in case of dirt or condensation around the camera in the front windshield. On vehicles equipped with front radar it can also occur if the area of the front radar unit is dirty/blocked by snow, mud. It is more likely that this appears more often during bad weather conditions as heavy rain, heavy snow fall or fog. Please advise the customer in case message appear to clean the front windshield around the front facing camera and front radar. In case of demist turn on the front windshield heating element and wait for windshield to demist. Do not install a new Front camera or recalibrate it. The display message is only a notice for the customer and is not a malfunction of vehicle components and will be disappear as soon as sensors are clean again.