



SSM 52302 Mondeo, S-MAX, Galaxy, Kuga, Focus with Headlamp Warning cluster message.

Headlamp Warning cluster messages may happen from time to time due to temporary communication issues between the headlamp control module and the headlamp internal actuators/motors. The customer should restart the vehicle, complete ignition cycle with engine off/on, to fix the issue. There is no real failure in the lamp as long as the cluster message is not popping up every day and the respective HCM DTC(s) are not always present/active. Please run relevant SBD Tests and consider published TSBs to check for "real" failures (SBDs: G2198350, G2005434, G2163629, G2163639, G2012846) (TSBs: No.22-2269, No.19-2307)