



SSM 51987 Various vehicles with 1.5/ 2.0L diesel engines. Warranty handling of Diesel Particulate Filter (DPF) replacement.

To support DPF replacement warranty claims there must be a DTC with "MIL on" indication included in the IDS session file. Claims without "MIL on" DTC's in the IDS session file will be returned to dealers for further clarification. DTC's that justify a replacement are P2002 The 2-digit status byte reported from the PCM must start with characters 8,9,A,B,C,D,E or F. DTC's without that qualifier are pending and do not indicate a failed part. Example: P2002-00-AE will be accepted, P2002-00-68 will be returned to dealers for further clarification. for further information regarding DPF diagnostics refer to GSB 21-7070 and GSB 23-7006